



**PREVENTIVE INSPECTIONS AND COMPLIANCE WITH SERVICE INTERVALS**  
**OF SR 2000 SERIES PROPELLER**

This Service Bulletin is issued in line with the procedures subject to LAA ČR no. 34/92 authorisation

Type certificate holder: <b>Aerospool, spol. s r.o.</b>	Type / Model: <b>SR 2000, SR 2000D, SR 2000DN</b> Three-bladed, in flight adjustable
Type certificate number	V-79/2003, V-80/2004
Related documents	N/A
Replaces	N/A
Manufacturer	Woodcomp Propellers s.r.o.
Applies to	Propellers installed on WT-9 Dynamic aeroplanes.
Reason	An event was reported on the WT9 Dynamic LSA (PtF) aircraft in which the propeller blade was lost during the service engine test of the propulsion unit on the ground. The aim of the test was to examine the cause of the increased vibrations of the aircraft propulsion unit.
Effective date	23 MAR 2021
Work procedure	N/A
Action	<p>The propeller manufacturer recalls that it is essential to follow the inspection intervals and service intervals prescribed in the propeller and aircraft documentation, as well as the procedures for troubleshooting. If a permanently increased level of vibrations of the propulsion unit is found compared to the state during commissioning, it is necessary to immediately stop the operation of the propeller, dismantle the propeller from the aircraft and send it to its manufacturer for inspection.</p> <p>Elevated vibration levels may not be directly related to the development of a propeller failure, but may be the cause. The manufacturer shall check the condition of the propeller and measure it to the extent not possible under normal operating conditions.</p> <p>In case of any doubt contact Woodcomp Propellers s.r.o. : Tel: +420 283 971 309 Mail: <a href="mailto:info@woodcomp.cz">info@woodcomp.cz</a></p>



**SERVICE BULLETIN**  
**No. UL 01/2021, Rev. 00**

Page: 2 / 2

Work to be performed by	a) Propeller disassembly and transport: Operator b) Inspection or repair: Woodcomp Propellers s.r.o.
Schedule	Immediately
Cost covered by	a) The operator according to the current price list for work performed as part of standard repairs and maintenance of airworthiness of the propeller. b) Woodcomp Propellers s.r.o. in the case of warranty repairs.
Material necessary	N/A
Remarks	N/A

Manager Accountable: Name: Aleš Křemen Sign:	Quality Manager: Name: Vilém Pompe Sign:	<b>Rev. 00</b> Date: 23 MAR 2021
--	--	--